www.morseindustries.com WHOLESALE ONLY: 800.325.7513



SQUARE POST SAFETY SHIELD INSTALLATION INSTRUCTIONS

SQUARE POST SHIELD KIT

The Square Post Shield provides the ability to pass money and small objects below the infill. The posts on this shield are manufactured from satin stainless steel which creates a high end appearance. The Square Post Shield works with a variety of infill material, accommodating thicknesses from 1/4" to 3/8". No fabrication is needed on the infill materials for the clamps.

2 people are recommended for this installation process - If the infill is tempered glass 2 people are REQUIRED

KIT INCLUDES (Part #: S54-2040BS):



(2pc) END CAP

Part #: R13-5728-040-12



(4pc) GLASS CLAMP

Part #: M13-2110-000-12

NOTE: (2) gaskets are required for each clamp



(2pc) SQUARE POST

Part #: R13-4900-040-12



(2pc) BASE FLANGE


Part #: R13-4505-040-12





STAINLESS STEEL ADHESIVE GLUE

Part #: R19-1331-000-00 (Sold Seperately - Each bottle covers around 10 installations)




www.morseindustries.com WHOLESALE ONLY: 800.325.7513




INSTALLATION

The following information will help you streamline set-up and installation.


1 Disassemble the clamps.









Attach the clamps to the post.




Glue the Flange to the bottom of the post.





Tap the End Cap into the top of the post.





www.morseindustries.com WHOLESALE ONLY: 800.325.7513






Place the infill into the clamps on one side. Screw the clamps closed around the infill. Place the infill into the clamps on the second post. Screw the clamps closed around the infill.

Set the infill so that the desired clearance exists between the substrate and the bottom edge of the infill

Different Gasket widths will be required for different infill widths.


Use the thicker gasket with 1/4" panel infill

Use the thinner gasket with 3/8" panel infill



6

Attach the shield to the substrate: Place the shield on the substrate in the final installation position. Mark the pilot hole positions using the screw holes in the flanges. Remove the shield from the substrate. Drill the marked pilot holes. Place the shield back on substrate and drive the screws into place.



For additional support call 800.325.7513 or visit our website www.morseindustries.com

